








Basics of Post-Tensioning / Prestressed Concrete

©2017 Structural Group, Inc.


struc'tural

# Prestressed Concrete Advantages Serviceability Controlling stresses Reduce cracking Reduce deflections Reduction in cross-section Weight savings Height savings Long spans

























# PT slabs can be modified to accept small and large penetrations • Mechanical and electrical penetrations (small) • Stair towers, elevator shafts (large) • With proper knowledge of structural behavior and PT experience, installing openings and other penetrations in PT slabs can be safely achieved






























































## Design / Construction Defects Defects in post-tensioning system engineering, detailing and installation may lead to: Slab edge splitting Tendon erupting through top or bottom of slab Concrete Spalling Resulting in potential property damage and personal injury













### Tendon "Blowouts": Anchorage Zone Common Causes: Inadequate or misplaced bursting steel Inadequate confining steel Low strength concrete Concrete voids in anchorage zone








### Solving Problems with Post-Tensioned Concrete





























































































## Strengthening Overview Used to increase the load-carrying capacity of reinforced concrete and other structure types Methods & Technologies Post-Tensioning FRP Composites Enlargement Supplemental Steel Epoxy Injection












# Strengthening with Enlargement & Overlays Overview: Bond additional reinforced concrete to structural members Utilizes pressurized formwork, proper surface preparation and specialized concrete materials to ensure proper bond / composite behavior Benefits: Ability to significantly add additional capacity to existing members Controls deflection High levels of fire resistance





### University of Pennsylvania - Parking Garage LOT 14

- Overview
  - Philadelphia, PA
  - 5-level / split level design (10 decks)
  - Built in 1960's
- Symptoms
  - Concrete delamination
  - Concrete spalling











struc'tural

### University of Pennsylvania - Parking Garage LOT 14

- PT System & Structure Evaluation Overview
  - The parking deck PT reinforced with 7 wire Buttonhead System and Cast-In-Place concrete ramps
  - Extreme weather conditions, de-icing salts and long time service has caused the concrete to delaminate and spall
  - Corrosion to the existing reinforcement has caused some of the buttonhead wires to fail



©2017 Structural Group, Inc.







struc'tural

### University of Pennsylvania - Parking Garage LOT 14

- Repair Design Overview:
  - PT Repair Strategy:
    - Partial tendon replacement using combination system technology
  - Concrete Repair Strategy:
    - Partial and full depth repair of concrete
  - Protection Strategy:
    - Installation of galvanic anode cathodic protection system
    - Trench drain and expansion joint replacement
       Waterproofing and roof level topping repairs














struc'tural






























# 1800 K Street Office Renovation - Roof Slab Opening Overview Washington, DC 11-floor building Built in 1970 (Buttonhead PT)

- Project Overview
  - Create slab opening for stairwell







struc'tural

# 1800 K Street Office Renovation - Roof Slab Opening

- Project Challenges
  - Tight working space due to obstructions (mechanical room, HVAC)
  - Tight schedule for completion (6 weeks)




Existing Mechanical Room: >>> Protection of equipment from dust and debris produced by demolition of slab to be constructed




struc'tur'al











































### Retail Parking Structure Strengthening

- Overview
  - Springfield, VA
  - Multi level precast parking structure
- Project Overview
  - Maximum vehicular weight capacity increased from 9,000 lbs. to 20,000 lbs.
  - Desired fire rating achieved using VStrand™ Heat Resistive Tendons









struc'tural

# Retail Parking Structure Strengthening


- Strengthening Design
  - Full-depth repair of cracked slab edges
  - 2.5-in. bonded reinforced concrete overlay for entire deck
  - Install steel brackets to support double tee flanges
  - Strengthen double tees using External PT

  - Strengthen inverted tees using bonded FRP composites
  - Strengthen inverted tee ledges w/ steel brackets





7 Structural Group, Inc.



struc'tural

### Retail Parking Structure Strengthening

• Bonded reinforced concrete overlay (2.5") for entire deck and full depth repairs





struc'tur'al







#### Baltimore Ave. Parking Structure - Detroit MI Overview Detroit, MI 4-level / split level design (7 decks 5 are elevated)

Built in 1960's

- Symptoms Concrete delamination/spalling
  - Embedded metal corrosion
  - Grout pocket deterioration
  - Exposed/Broken PT Tendons
  - Beam/slab deflection/cracking
  - SOG settlement
  - Poor drainage
  - Poor lighting







struc'tural

## Baltimore Ave. Parking Structure - Detroit MI

- PT System & Structure Evaluation Overview
  - Buttonhead Wire parking deck floor slab system, Precast PT Beams with 2- 20 wire bundles and conventionally reinforced concrete ramps
  - Extreme weather conditions, poor drainage, de-icing salts and long time service has caused the concrete to delaminate and spall
  - Corrosion to the existing reinforcement and PT hardware had caused many of the wires to corrode and break



02017 Structural Group, Inc. 4PREV CASE STUDIES NEXT >



struc'tural

#### Baltimore Ave. Parking Structure - Detroit MI

- Repair Design Overview:
  - PT Slab Repair Strategy:
  - 234 Unbonded partial tendon replacements using combination system technology
  - PT Beam Repair Strategy:
    - 32 External post-tensioning repairs utilizing existing threaded bar anchorages, new post tensioning tendons, deviators and new steel couplers.
  - · Concrete Repair Strategy:
  - Partial and full depth repair of concrete

  - Protection Strategy:
     Encapsulated connections to existing beam anchorages
    - Grout external XPT<sup>TM</sup> tendons
       Fire resistant coatings to steel deviators

    - Expansion joint replacementsImproved drain system







struc'tur'al

